



# HOT LINE NEWSLETTER

JE-01-92  
REVISED

March 9, 1992

**IN ITEM B OF HOT LINE NEWSLETTER JE-01-92, DATED JANUARY 27, 1992, A PART NUMBER WAS PRINTED INCORRECTLY. PART NUMBER 4369000 SHOULD HAVE READ 4639000. THIS CORRECTION HAS BEEN HIGHLIGHTED BELOW WITH \*\* ASTERISKS \*\* AND IS PRINTED IN RED. HOT LINE JE-01-92 SHOULD BE REMOVED FROM YOUR FILE AND REPLACED WITH THIS REVISED EDITION.**

ITEM A: INTERIOR TRIM GLOSS LEVELS

MODELS: ALL MODELS

GROUP: 23 - BODY

ACTION: The gloss level of interior trim components in all Chrysler Corporation vehicles is a dull flat finish by design. Dealers or their agents should not apply any coatings (or cleaners with enhancers) on interior components that will change the dull flat finish.

ITEM B: WIRING CONNECTOR REPLACEMENT PACKAGES

GROUP: 08 - ELECTRICAL

ACTION: To improve serviceability and make effective repairs, additional electrical connector repair packages have been developed. The connector repair packages eliminate the need for replacing a complete wiring harness when only a connector is required.

All packages contain a connector with the base color coded wires already installed and heat shrinkable tubing to cover the solder joints. The following items are now available.

.....  
Index # **027519**  
.....

continued. . . . .

JE-01-92  
REVISED

-2-

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>APPLICATION</u>
4419590	2-Way 0.045" Connectors	87-92 All Models
4638997	3-Way TPS Connector	91 1/4 BB
4638998	3-Way MAP Sensor	91 1/4 BB
**4639000**	3-Way Speed Sensor	88-92 BB
4419582	.045 in. Terminal Wire	88-92 All Models
4419584	2-Way Fuse Holder	89 BC
4419585	2-Way Fuse Holder	91 All Models