

TECHNICAL SERVICE BULLETIN

SUBJECT:
Exhaust Noise

NO.: 11-03-92
GROUP: Exhaust
DATE: Nov. 2, 1992

This Bulletin is Supplied As Technical Information Only And is Not An Authorization For Repair. Reprint Of This Material Not Authorized Unless Approved.

NOTE: THIS BULLETIN APPLIES TO VEHICLES EQUIPPED WITH 1.8L ENGINE.

MODELS:

1989-1992 (BD) Laser/Talon

SYMPTOM/CONDITION:

Some vehicles built prior to January 28, 1992 may exhibit a noise/exhaust leak from the center exhaust pipe at the sub-muffler. This condition may be corrected by replacing the center exhaust pipe with a revised center exhaust pipe.

PARTS REQUIRED:

1 Center Exhaust Pipe MB906622

NOTE: THE REVISED CENTER EXHAUST PIPE DOES NOT HAVE A SUB-MUFFLER AND IS INTERCHANGEABLE WITH THE EARLIER STYLE.

REPAIR PROCEDURE:

This repair involves replacing the center exhaust pipe with a revised pipe.

1. Remove the center exhaust pipe as outlined in the appropriate service manual.
2. Install the revised exhaust pipe (PN MB906622).

POLICY: Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No. 11-20-01-91 0.6 Hrs.

FAILURE CODE: P8 - New Part
P-3851

Index # **030705**

