



WA

HL-18-92

Apr. 21, 1992

NOTE: THIS HOT LINE NEWSLETTER CONTAINS INFORMATION THAT HAS BEEN PROVIDED TO THE CHRYSLER, PLYMOUTH AND DODGE DEALERS IN HL-04-92 AND HL-10-92. THIS INFORMATION HAS BEEN COMBINED INTO ONE HOT LINE NEWSLETTER AND IS BEING ISSUED TO ALL CHRYSLER, PLYMOUTH, DODGE AND EAGLE DEALERS.

ITEM: WIRING CONNECTOR REPLACEMENT PACKAGES

GROUP: 08 - ELECTRICAL

ACTION: To improve serviceability and make effective repairs, additional electrical connector repair packages have been developed. The connector repair packages eliminate the need for replacing a complete wiring harness when only a connector is required.

All packages contain a connector with the base color coded wires already installed and heat shrinkable tubing to cover the solder joints. The following items are now available.

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>APPLICATION</u>
4419555	15 & 18 Way VMM Trip Computer	1988-92 BB
4419558	32-Way HVAC & Headlight Control	1988-92 BB
4419560	12 & 18 Way Cluster	1988-92 BB
4419564	12 & 18 Way Passive Restraint Module	1988-92 BB
4638993	Passive Restraint Relay Connector	1988-92 BB
4638992	2-Way Low Pressure Switch	1988-92 BB
4638995	3-Way MAP Sensor Connector	1990 BB
4638999	8-Way Speed Sensor Processing Module	1988-92 BB
4638994	3-Way TPS Connector	1990 BB